

MobileMark 2018 patch 1 v1.0.1.39

Release notes: 25 Mar 2019

General Notes:

- Supports Win 10 (64 bit) - RS3 (1709) and above
- Reference system: Lenovo ThinkPad T480s
 - CPU: Intel Core i5-8250U @ 1.60 GHz
 - Graphics: Intel HD 620
 - Resolution: 1920x1080
 - Display Brightness: 200 nits
 - OS build version: Win 10 RS4 build 10.0.17134.228 (64bit)
 - RAM: 1 X 8GB (Single Channel)
 - Storage: 256 GB Solid State Drive, PCIe-NVMe OPAL2.0 M.2
- Included scenarios
 - Productivity (PR)
 - Included PR applications
 - Microsoft Word 2016
 - Microsoft Excel 2016
 - Microsoft PowerPoint 2016
 - Microsoft OneNote 2016
 - Microsoft Outlook 2016
 - Adobe Acrobat DC
 - AutoIT 3.3.14.2
 - Creativity (CR)
 - Included CR applications
 - Adobe Photoshop Lightroom Classic
 - Adobe Photoshop CC 2018
 - Cyberlink PowerDirector 15
 - Web Browsing (WB)
 - Included WB applications
 - Google Chrome 70
 - Microsoft Movies & TV
- Calibration score: 1000
- Must not run on a live Internet connection.

Fixes/Updates

- Improved detection and reporting of Windows 10 Performance/Power slider position
- Config tool now sets Windows search service to 'On'
- Updated non-English language translations
- Installer now prevents deselecting components prior to installation
- Fixed issue with system information on French language OS
- Initialization section will now timeout if the system is unresponsive for more than two hours

Known issues

- If the system under test was running on Windows 10 RS2 (1703), the low battery notification dialog will appear when battery level is low and causes the test to fail.
- Microsoft OneDrive crashes on some systems and interferes with benchmark run
 - Workaround: Uninstall OneDrive before installing benchmark
- OneNote email workload may select UWP version of Outlook which causes the workload to error. Workaround is to set default application to Outlook 2016.
- Microsoft Office application workloads will fail if a pre-existing installation of Office is not completely cleaned out before install. This includes Microsoft Office UWP apps, as well as any OEM installed Office trial copies.
 - Office Removal tool: <https://support.office.com/en-us/article/Uninstall-Office-from-a-PC-9dd49b83-264a-477a-8fcc-2fdf5dbf61d8>
 - Reboot, then
 - Cleanout registry if necessary: <https://support.office.com/en-us/article/office-repeatedly-prompts-you-to-activate-on-a-new-pc-a9a6b05f-f6ce-4d1f-8d49-eb5007b64ba1>
- Translation on some supported foreign languages is not complete.